LAWNMOWER

Mistakes to avoid when using a trimmer or blower

- **Incorrect nylon line:** These differ in size and vary according to the type of machine
- **Intermittant stop/start of motor:** Can cause the motor to burn out
- **Excessively long extension cord:** Affects voltage power & must not exceed 30 metres

011 803-1241
info@mrlawnmower.co.za
www.mrlawnmower.co.za
369 Rivonia Blvd, off 11th ave, Rivonia